MITSUBISHI MOTOR SALES OF AMERICA, Inc.

TECHNICAL SERVICE BULLETIN

SUBJECT:

1988 TRUCK SIDE WINDOW SPACER

9/14/88

NO.	TSB-88-23-010
DATE	August, 1988
MODEL	1989 Truck

TSB Revision TSB-88-23-010

PURPOSE

This bulletin is issued to correct the text and illustrations pertaining to the installation of the side window glass in the 1988 trucks. The production change described in this bulletin has been in effect since Job #1, 1988 model year. As reference to this bulletin, please write the TSB number in the revision boxes at the bottom of Pages 23-27 and 23-28 in the 1988 Truck Service Manual, Vol.1.

REVISIONS

Page 23-27: The lower window spacer is not used, and a center spacer is added as shown in the illustration below.

BODY – Side Window Glass 23-27

SIDE WINDOW GLASS

REMOVAL AND INSTALLATION



Removal steps

- ◆◆ 1. Center pillar garnish
- 2. Trim clip
- ◆◆ 3. Side window lower molding
- 4. Window molding clip
- 5. Glass holder
- ◆◆6. Side window glass
- ◆◆7. Window spacer
- 8. Side window spacer

NOTE
(1) Reverse the removal procedures to reinstall.
(2) ◆◆ : Refer to "Service Points of Removal".
(3) ◆◆ : Refer to "Service Points of Installation".

012436

continued...

FILE UNDER:
Group 23 Body and Sheet Metal in the 1988 Technical Service Bulletin Binder

2657

CIRCULATE TO:

- ☐ GENERAL MANAGER
- ☐ PARTS MANAGER
- ☑ TECHNICIAN
- ☐ SERVICE ADVISOR
- ☑ SERVICE MANAGER
- ☐ WARRANTY PROCESSOR
- ☐ SALES MANAGER

(532)

Page 23-28: Revise the illustration on this page as shown.



SERVICE POINTS OF INSTALLATION

7. INSTALLATION OF WINDOW SPACER

Align the window spacer with the edge of the windc
ing clip and install in the position shown in the diagr